

INSTRUCTIONS PHOTO ETCHED DETAILS
FOR BORDER BS-001 TYPE: VIIC U-552 / U-96 / U-82 1/35



SKU-086




Description of patrs




this kit is only basic and does not fix the major deck flaws of this model. The main flaw of the model is the upper wind collar, which is wrong, so I recommend the item from 3 d printing SKU-L-552 or 96 or 82. For the U-82 submarine version, item SP-82 side antenna panel must be used. the submarine has a very bad shape of deck hatches, wrong size, height and diameter. We produce new versions of the hatch, early version without cover plate, late version with cover plate.

TOWER










the upper collar has a very bad and unrealistic shape.
We recommend using our 3D print repair kit.
Collar we have the exact shape for individual submarines U-552 / U-96 / U-82.





removed - level the surface

Border plastic hatches
(this hatch has the wrong shape and dimensions)




DECK







the forward hatch for the buoy was at an angle of 3°




it is necessary to adjust the opening in front of the hatch





DECK





hatch axis is below deck
the hatch is clean and has no locks
7xD2
24xP1
12xD6
D11
D9
D10
H3
H2
axis Ø1,5 mm
H4
H3
H5
H4
H5
2xD8
D5
5xD7
2xD3
D4

TOWER






ONLY U-552 / U-96
T20
90°
90°
2x
T24
T24
T22
2x
T14
T21
90°
90°
T23
SKU-L-552 or 96 or 82
2x
T22
90°
90°
T19
2x
ONLY U-552 / U-96
T15
T10
T10
T9
T9
T3
2x
T11
T10
T11

U-552


SKU-FISO
SKU-L-552
REPAIR COLLAR
SKU-065
SKU-RISO
T21
T15
T10
T19
T22
2xT9
T20
T12
T14
180°
G2
G2
T5
T4
T10
9xT11
T4.1
T13
T10
T3
T6
T7
2xT8
T17
T16
T6
T7
2xT8
D11
D11
H2
H3
D11
G1
H2
H3
H1
H1
H1
SKU-082
2xT18

U-96


SKU-L-96
REPAIR COLLAR
SKU-065
T21
T15
T10
T19
T22
2xT9
T20
T12
T14
180°
G2
G2
T5
T4
T10
9xT11
T4.1
T13
T10
T3
T6
T7
2xT8
T17
T16
T6
T7
2xT8
D11
D11
H2
H3
D11
G1
H2
H3
SKU-082
2xT18


SKU-SP-82
SIDE ANTENNA PANEL
SKU-FISO
SKU-L-82
REPAIR COLLAR
U-82
SKU-SP-82
SKU-065
T21
T15
T10
2xT9
T22
T12
T14
T4.1
180°
G2
G2
T5
T4
T10
9xT11
T4.1
T13
D11
T3
T6
T7
2xT8
T17
T16
T6
T7
2xT8
T10
H2
H3
D11
G1
H2
H3
D11
SKU-082
2xT18
L1
L1
L2
L3
L4