INSTRUCTIONS PHOTO ETCHED DETAILS
FOR BORDER BS-001 TYPE: VIIC U-552 / U-96 / U-82 1/35



SKU-082










SKU-SP-82



SKU-RISO





SKU-L-96



SKU-FISO




SKU-L-82



SKU-065






SKU-L-552




Description of patrs


SKU-082



the flag sail must be painted white before the decal is installed








the upper collar has a very bad and unrealistic shape.
We recommend using our 3D print repair kit.
Collar we have the exact shape for individual submarines U-552 / U-96 / U-82.

this plastic must be removed






The submarine had insulators on both the front and rear of the turret. It can be seen in all photos of U-552. The rear insulators were placed in special tubes.


U-552


SKU-065



SKU-L-552








the plug must be inserted from the back of the main etching

SKU-RISO



SKU-FISO





the plug must be inserted from the back of the main etching

U-96


SKU-065


The original Border decal has the wrong fish shape


SKU-L-96




Decal-96








Decal-96




U-82

SKU-SP-82


SIDE ANTENNA PANEL




SKU-L-82



SKU-065





SKU-FISO



the plug must be inserted from the back of the main etching